

## Water Quality Chemistry Services Lead School Testing Report Date: 28-Apr-2017

## San Diego Unified School District Henry High School

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1167211	4/18/2017	6:06 AM	SAMPLE 1	3710020-AFG-A	6.34	μg/L
W1167212	4/18/2017	6:18 AM	SAMPLE 2	3710020-AFG-B	< 5	μg/L
W1167213	4/18/2017	6:21 AM	SAMPLE 3	3710020-AFG-C	< 5	μg/L
W1167214	4/18/2017	6:26 AM	SAMPLE 4	3710020-AFG-D	< 5	μg/L
W1167215	4/18/2017	6:37 AM	SAMPLE 5	3710020-AFG-E	< 5	μg/L

<u>Source</u>	Source Description
SAMPLE 1	Auditorium/stage/Prop room;Eastside exterior between custodian 6 door and M RR; L and upper single bubbler of 2 single fountains
SAMPLE 2	East interior wall of Kitchen; 2 compartment sink, faucet
SAMPLE 3	300 bldg. west end, Restrooms; R side lower bubbler of 2 single fountains
SAMPLE 4	100 BLDG; Exterior S Side next to Girl's RR; L lower bubbler of 2 single fountains
SAMPLE 5	PRE-K BUNGALOW B-101; Bubbler water fountain R side of sink inside classroom

DRL=State Mandated Detection Limit for Reporting (DLR)= 5  $\mu$ g/L Action Level (AL) = 15  $\mu$ g/L

Doug Campbell, Senior Chemist